

**Flood Control Project Maintenance
Levee Inspections****LMA District Cover Sheet****Spring 2011 Levee Inspection Results****Reclamation District No. 0010 Honcut**

| | Spring (March - May) | Summer ** (June - August) | Fall (September - November) | Winter ** (December - February) |
|----------------------------------|-------------------------|------------------------------|--------------------------------|------------------------------------|
| * Overall LMA Rating (Fall Only) | | | | |

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

| |
|--|
| |
| |
| |
| |
| |
| |
| |

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 0010 Honcut

| Waterway | | | Bank | Unit Miles |
|-----------------------------|--|--|-------|------------|
| Unit No. 01 Simmerly Slough | | | Right | 7.68 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2011 - 5/26/2011 | | | |
| DWR Inspector | Clay Thomas | | | |
| Accompanied By | Finlay Williams | | | |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0010 Honcut

| Waterway | | | | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------|--|--|--|--|--|-------|------------|--------------------------|-------------|
| Unit No. 01 Simmerly Slough | | | | | | Right | 7.68 | 05/26/2011 05/26/2011 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | * Location | ** Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|------------|------------|-----------|---|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.00 | 7.67 | Earthen Levee | Vegetation | WS | M | Control annual grass and weeds on the levee slopes and easements. | 39.163714 ° -121.609941 ° | 39.256048 ° -121.574920 ° | 2 Y |
| 2 | 0.00 | 7.67 | Earthen Levee | Vegetation | LS | M | Control annual grass and weeds on the levee slopes and easements. | 39.163714 ° -121.609941 ° | 39.256048 ° -121.574920 ° | 3 Y |

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0010 Honcut

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|-----------------------------|-------|------------|--------------------------|-------------|
| Unit No. 01 Simmerly Slough | Right | 7.68 | 05/26/2011 05/26/2011 | Clay Thomas |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 7.67 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |

Levee mile 7.67, this photo shows the vegetation on the waterside slope.

cathom_s_20110531_197.jpg



| | |
|------------------------|---------------|
| Levee Mile Report Line | 2 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 7.67 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |

Levee mile 7.67, this photo shows the vegetation on the landside slope.

cathom_s_20110531_196.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 0010 Honcut

| Waterway | | | Bank | Unit Miles |
|---------------------------|--|--|------|------------|
| Unit No. 02 Feather River | | | Left | 11.24 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2011 - 5/26/2011 | | | |
| DWR Inspector | Clay Thomas | | | |
| Accompanied By | Finlay Williams | | | |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0010 Honcut

| Waterway | | | | | | Bank | Unit Miles | Inspection Start/End | | Inspector |
|---------------------------|--|--|--|--|--|------|------------|--------------------------|--|-------------|
| Unit No. 02 Feather River | | | | | | Left | 11.24 | 05/26/2011 05/26/2011 | | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|----------------|----------|--------|--|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.00 | 11.19 | Earthen Levee | Vegetation | WS | M | Control annual grass and weeds on the levee slopes and easements. | 39.163714 ° -121.609940 ° | 39.307024 ° -121.617313 ° | 2 Y |
| 2 | 0.00 | 11.19 | Earthen Levee | Vegetation | LS | M | Control annual grass and weeds on the levee slopes and easements. | 39.163714 ° -121.609940 ° | 39.307024 ° -121.617311 ° | 1 Y |
| 3 | 1.35 | 1.35 | Earthen Levee | Encroachments | LS | PO | Landscaping | 39.182957 ° -121.609800 ° | 39.182957 ° -121.609800 ° | 9 |
| 4 | 6.27 | 6.27 | Earthen Levee | Encroachments | LS | C | Debris | 39.251905 ° -121.619202 ° | 39.251905 ° -121.619202 ° | 7 |
| 5 | 7.10 | 7.10 | Earthen Levee | Animal Control | LS | C | No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. | 39.262316 ° -121.614376 ° | 39.262316 ° -121.614376 ° | 18 |
| 6 | 7.59 | 7.59 | Earthen Levee | Encroachments | LS | C | Debris | 39.268841 ° -121.611425 ° | 39.268841 ° -121.611425 ° | 35 |
| 7 | 9.30 | 9.30 | Earthen Levee | Encroachments | LS | M | Prunings | 39.285883 ° -121.600353 ° | 39.285883 ° -121.600353 ° | 3 Y |
| 8 | 10.74 | 11.11 | Earthen Levee | Vegetation | WS | M | Remove the wild growth other than native grasses from the levee slopes. | 39.300812 ° -121.617528 ° | 39.305892 ° -121.617715 ° | 23 |

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0010 Honcut

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|---------------------------|------|------------|--------------------------|-------------|
| Unit No. 02 Feather River | Left | 11.24 | 05/26/2011 05/26/2011 | Clay Thomas |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 11.19 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |

Levee mile 6.70, this photo is looking at the vegetation on the waterside slope.

cathom_s_20110531_192.jpg



| | |
|------------------------|---------------|
| Levee Mile Report Line | 2 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 11.19 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |

Levee mile 6.70, this photo is looking at the vegetation on the landside slope.

cathom_s_20110531_193.jpg



| | |
|------------------------|---------------|
| Levee Mile Report Line | 7 |
| Start Levee Mile | 9.30 |
| End Levee Mile | 9.30 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Encroachments |

Land side levee mile 9.30.

cathom_s_20110228_063.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 0010 Honcut

| Waterway | | | Bank | Unit Miles |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit No. 03 Honcut Creek | | | Left | 3.01 |
| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
| Unit Maintenance Rating (Fall Only) | | | | |
| Date of Inspection | 5/26/2011 - 5/26/2011 | | | |
| DWR Inspector | Clay Thomas | | | |
| Accompanied By | Finlay Williams | | | |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0010 Honcut

| Waterway | | | | | | Bank | Unit Miles | Inspection Start/End | Inspector |
|--------------------------|--|--|--|--|--|------|------------|--------------------------|-------------|
| Unit No. 03 Honcut Creek | | | | | | Left | 3.01 | 05/26/2011 05/26/2011 | Clay Thomas |

| LMIR No. | Levee Mile | | Category | Item | * Location | ** Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. |
|----------|------------|------|---------------|-------------------|------------|-----------|---|------------------------------|------------------------------|-----------|
| | Start | End | | | | | | Start | End | Photo |
| 1 | 0.00 | 2.89 | Earthen Levee | Vegetation | LS | M | Control annual grass and weeds on the levee slopes and easements. | 39.307868 ° -121.617070 ° | 39.299152 ° -121.571802 ° | 3 Y |
| 2 | 0.00 | 2.89 | Earthen Levee | Vegetation | WS | M | Control annual grass and weeds on the levee slopes and easements. | 39.307869 ° -121.617070 ° | 39.299152 ° -121.571801 ° | 1 Y |
| 3 | 0.17 | 0.17 | Earthen Levee | Trim / Thin Trees | WS | C | Trim trees over roadway to at least 12 feet above ground level. | 39.310032 ° -121.616338 ° | 39.310032 ° -121.616338 ° | 2 |
| 4 | 1.68 | 1.68 | Earthen Levee | Encroachments | WS | M | Debris | 39.303751 ° -121.591416 ° | 39.303751 ° -121.591416 ° | 4 |
| 5 | 2.81 | 2.81 | Earthen Levee | Vegetation | WS | M | Remove the wild growth other than native grasses from the levee slopes. | 39.299653 ° -121.573072 ° | 39.299653 ° -121.573072 ° | 6 |

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 0010 Honcut

| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
|--------------------------|------|------------|--------------------------|-------------|
| Unit No. 03 Honcut Creek | Left | 3.01 | 05/26/2011 05/26/2011 | Clay Thomas |

| | |
|------------------------|---------------|
| Levee Mile Report Line | 1 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 2.89 |
| Location | Land Side |
| Category | Earthen Levee |
| Item | Vegetation |

Levee mile 0.02, this photo is looking at the vegetation on the landside slope.

cathom_s_20110531_194.jpg



| | |
|------------------------|---------------|
| Levee Mile Report Line | 2 |
| Start Levee Mile | 0.00 |
| End Levee Mile | 2.89 |
| Location | Water Side |
| Category | Earthen Levee |
| Item | Vegetation |

Levee mile 0.02, this photo is looking at the vegetation on the waterside slope.

cathom_s_20110531_195.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor